CERTIFICATE **FITNESS**

To be filled by the Inspecting Officer (Asst. Engineer)

(Re: G.O. Ms. 20/70/ PWD Dt. 23 - 01 -1970)

Name of the Officer

Mrs. Anila

Asst. Engineer, LSGD Section, East Kadungalloor, Aluva

Name of the School

Rajashree S M M School, East Kadungalloor, Aluva

Location with name of Education District/ Sub. District:

East Kadungalloor-Ernakulam - Aluva

Classification of Building as specified in column 4 of the application for fitness certificate and size,

Number of classrooms - 60 Nos. PERMANENT, MULTI STORIED

PERMANENT _ MULTI-STORIED

Kindergarten - (13.85x5.16x3) x 2 + (15.30x9.12x3) x2 + 10.70x5.2x3

Kindergarten 1 & 2 - (13.30x15.10x3) x 2

LP / Primary block - (30.48x8.95x3.04) x 2 + (29.06x9.46x3.04) x 2 + (17.72x12.58 x 3.04) x 2

UP/Secondary Block - (30.70x9.18x3) x 3 + (30.70x9.18x3) x 3 + (2.9x6.8x3) x 3

Office - (19.10x8.18x3.5) x 3 + (17.12x10.52x3.5) x 3 + (5.70x8.1x3.5) x 3

2024-25 Period for which the certificate is issued

Nature of defects, if any

Nil a) Foundation and basement

Nil b) Superstructure

Nil c) Doors and Windows

Nil d) Wood work wrought and put up Nil

e)Roof

Nil f) Flooring Nil

g) Miscellaneous (Cracks, etc.)

Any major defects noticed which will render the building unsafe in any manner

· No

- Whether maintenance works have been done properly : NA (Old construction, Not directly supervised by the LSGD)
- Whether the structure is sound or not for conducting classes Yes, under normal weather conditions

Certified that the school building was inspected by me on 18,10,2024 and found to be fit / wafft to conduct classes, for the period 2024-25 for the reasons stated above.

Place: Kadungalloor

Date: 18,10.2024

THE ASS GRAMA PANCY

LID & EW SECTION ADUNGALLOOR GRAMA PANCHAYATH

C.S. KRISHNAKUMAR, M.A. BEd.

Principal Rajashree S.M. McCanhadlowith ACE Scanner East Kadungalloor, Aluva - 2

Ernakulam