



# കടുങ്ങല്ലൂർ ഗ്രാമ പഞ്ചായത്ത്

അസിസ്റ്റന്റ് എൻജിനീയറുടെ കാര്യാലയം  
എൽ ഐ ഡി & ഇ ഡബ്ല്യു സെക്ഷൻ  
മുപ്പത്തടം പി ഓ ,ആലുവ,പിൻ:683110  
email:aelsgdkdlr@gmail.com

NO.43/AE/KDLR/2025-26

From,

അസിസ്റ്റന്റ് എഞ്ചിനീയർ  
എൽ എസ് ജി ഡി സെക്ഷൻ  
കടുങ്ങല്ലൂർ ഗ്രാമ പഞ്ചായത്ത്

To,

പ്രിൻസിപ്പൽ  
ദി ഹെറിറ്റേജ് സ്കൂൾ  
ഇന്ത്യ കടുങ്ങല്ലൂർ  
ആലുവ

സർ,

വിഷയം : ഫിറ്റ്നസ് നൽകുന്നത് സംബന്ധിച്ച്  
സൂചന : ടി ഓഫീസിൽ 14/07/2025-ൽ ലഭിച്ച കത്ത്

മേൽ സൂചന പ്രകാരം ലഭിച്ച കത്തിന്റെ അടിസ്ഥാനത്തിൽ പുതുക്കിയ നാമത്തിലുള്ള (THE HERITAGE SCHOOL) സ്കൂളിന്റെ ഫിറ്റ്നസ് ഇതോടൊപ്പം ഉൾപ്പെടുത്തുന്നു.

കടുങ്ങല്ലൂർ  
21.07.2025



വിശ്വസ്തയോടെ,

ASSISTANT ENGINEER  
OFFICE OF THE ASSISTANT ENGINEER  
LID & EW SECTION  
KADUNGALLOOR GRAMA PANCHAYATH

C.S. KRISHNAKUMAR, M.A. BEd  
Principal  
The Heritage School  
East Kadungalloor, Aluva - 2  
Ernakulam

# FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Asst. Engineer)  
(Re:G.O.Ms.20/70/PWD Dt.23-01-1970)

1. Name of the Officer :- ANILA REGHUNATH
2. Name of the School :- THE HERITAGE SCHOOL
3. Location with name of Education District/Sub. District :- EAST KADUNGALLOOR, ALUVA, ERNAKULAM
4. Classification of Building as specified in column 4 of the :- PERMANENT, MULTI STORIED  
Application for fitness certificate and size.

5. Period for which the certificate is issued : Academic Year - 2025-26

6. Nature of defects, if any

- a) Foundation and basement
- b) Superstructure
- c) Doors and windows
- d) Wood work wrought and put up
- e) Roof
- f) Flooring
- g) Miscellaneous (Cracks etc)

.....  
.....  
.....  
..... NIL .....  
.....  
.....

7. Any major defects noticed which will render the building unsafe in any manner :- NO

8. Whether maintenance works have been done properly :- YES

9. Whether the structure is sound or not for conducting classes : Structure is Sound under normal weather condition.


Note : 1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure of flood etc. 2. Any additional observations if deemed necessary for the certificate may be furnished separately with this certificate.


## CERTIFICATE

Certificate that the Anganwadi was inspected by me on ...31.05.2025... and Found to be fit /unfit to conduct classes, for the period Academic Year 2025-26 for the reasons stated above.

Place: Kadungalloor  
Date: 21.07.2025

  
C.S. KRISHNAKUMAR, M.A. Bsc  
Principal  
The Heritage School  
East Kadungalloor, Aluva - 2  
Ernakulam



  
Assistant Engineer  
OFFICE OF THE ASSISTANT ENGINEER  
LID & EW SECTION  
KADUNGALLOOR GRAMA PANCHAYATH

## BUILDING DETAILS

### KINDERGARTEN

GF & FF – (13.85 x 5.16 x 3) x 2 + (15.30 x 9.12 x 3) x 2 + (10.70 x 5.2 x 3) x 2

### KINDERGARTEN 1&2

GF & FF – (13.30 x 15.10 x 3) x 2

### LP / PRIMARY BLOCK

RCC GF- (30.48 x 8.95 x 3.04) x 1 + (29.06x9.46x3.04) x 1 + (17.72 x 12.58 x 3.04) x 1

FF- (29.06x9.46x3.04) x 1 + (17.72 x 12.58 x 3.04) x 1

### UP / SECONDARY BLOCK

GF,FF,SF- (30.70 x 9.18 x 3) x 3 + (30.70 x 9.18 x 3) x 3 + (2.9 x 6.8 x 3) x 3

### OFFICE

(19.10 x 8.18 x 3.5) x 3 + (17.12 x 10.52 x 3.5) x 3 + (5.70 x 8.1 x 3.5) x 3



*[Signature]*  
ASSISTANT ENGINEER  
OFFICE OF THE ASSISTANT ENGINEER  
LID & EW SECTION  
MADUNGALLOOR GRAMA PANCHAYATH

*[Signature]*

C.S. KRISHNAKUMAR, M.A. Bed.  
Principal  
The Heritage School  
East Kadungalloor, Aluva - 2  
Ernakulam